FIELD INSPECTION REPORT

Division: Thanjharpuy			District: Madhubani Length (km): 0.275 K	W
lame of	the Road:	Bhaire	av Stranse Raigem Jane wate Pa	th ki Mara
cheme/	Programme:	MAINTENAN	CE STATE OF THE ST	
Package No.:			Road Id No.: 319098080.81	
	f the Project:			Mantan
Vork is	a case of:	New Connectiv	rity/Up gradation/ Maintenance out	of mainta
SI. No.	Parameter		rs to be checked	Remarks
1.	Pavement			
a)	Road Junction	n condition		S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: MD GYASUDDINA

DESIGNATION: AZ