FIELD INSPECTION REPORT

Date of Inspection: 11/20 District: Madhubam Length (km): 0.386 km Name of the Road: Kamla Paschmi Tattandh Gadrya se Naruagi Iane Wali Pa Scheme/Programme: MAINTENANCE Package No.: Road Id No.: 31909808085				
Division :	Thanjhaspor	Length (km): 0.386 PM	James Jane	Wall
Name of t	he Road: Kamla Hasch	ini Tatbondh Gadryuse D	a lace-	4)4134"
Scheme/P	rogramme: MAINTENANCE	Bood Id No. Digageng 08	-	
Package N	No.:	Winder Maintenance	of Maintau	L
	the Project: Ongoing/Completed	p gradation/ Maintenance out	of maintage	
Work is a		Marie III	Remarks	1
SI. No.	Parameters to	be checked	Keman	1
1.	Payement	and the state of the said	Appendig to	1
to dis Production	Road Junction condition		S/U	
a)			S/U	Roadis
b)	Condition of Surfacing		S/U	Road 18 Out of Mainten
c)	Riding Quality		S/U	6
d)	Road Camber		Mainteu	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f)	Contraction Joints provided or not (Yes/No		
g)	Compaction of flank/slope & raincu	Yes/No	N.A	
· 2.	Cross Drainage	the state of the s	AND THE PROPERTY OF	\
a)	Condition of head walls in Hume pi	pe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing wa	lls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory stones/Pavement road markings are	provided and maintained	Yes/No	
4.	Compliance History			,
a)	Status of ATR's & any others		-	
		9		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: MD GYASUDDIYY

DESIGNATION: AE