

FIELD INSPECTION REPORT

Date of Inspection : 07.12.2020		District: Madhubani
Division : Phulparas		Length (km): 1.420 km
Name of the Road: Toz to Auraha		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 319022 02010
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance		
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

New agreement Dt. 23.11.2020. Work not started yet

(Signature)

NAME:

Gampati Jha

DESIGNATION:

A.E.

07.12.2020
J.E.

7/12/20
AE