FIELD INSPECTION REPORT

Date of Inspection: 07.12.2020		District: Madhubani		
Division: Phulpanas		Length (km): 3.350 KM		
Name of the Road: To4 to Mahthown Goth				
Scheme/Programme: MAINTENANCE				
Package No.:		Road Id No.: 2120202012		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber ·	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
. 2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	The state of the s

Overall Rating

Satisfactory (S)	2_
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started yet

(Signature)

NAME: Gampati Tha

DESIGNATION: A.E.

07.12.20 Af