

FIELD INSPECTION REPORT

Date of Inspection	5-12-2020	Inspector	Madhavi
Division	Banipatti	Length (km)	2.40 km
Name of the Road	Saharghat To Mahua Road	Package No.	R11/NNBN/19/18
Scheme/Programme	CC, 11.5, 4.5	Road ID No.	31915001631
Status of the Project	Upgrading completed	Current Maintenance	
Work is a case of	New Construction / Upgradation / Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Surface condition	NT
b)	Condition of Surfacing	NT
c)	Riding Quality	NT
d)	Road Surface	NT
e)	Whether free from defects such as surface cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bank/slope & rainouts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/dab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

WORK NOT STARTED
TILL DATE

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

N/A

NOTE ① Jungle Clearing work is progress

② Pot Patch & SDBC work is pending

(Signature) Bhaskar
5-12-2020

NAME: Madam Chandhary

DESIGNATION: J.E