

FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020 Name: Madhubani
 Division: Patna District Length: 0.650 Km
 Name of the Road: NH-78 to Madhubani
 Scheme/Programme: CCN/1/2019-20
 Package No: ER/HAIPEN/1/13 Road ID No: 71910802078
 Name of the Project: Improving connectivity to Madhubani
 Work to be done: New 1 km stretch of 11m wide road

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Visual inspection condition	✓
b)	Condition of Bituminous	✓
c)	Width/Quality	✓
d)	Street Curb	✓
e)	Whether any other defects such as surface cracks, exposed aggregates in case of CC Pavement	Yes/No N/A
f)	Construction joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of fresh slope & surface of sub	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including on pointing	✓/N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/N/A
c)	Condition of railings/slab approach for Bridges	S/N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Madhubani
 05-12-2020
 (Signature)

NAME: Madan Chaudhary

DESIGNATION: J.E.