

FIELD INSPECTION REPORT

Date of Inspection: 02-12-2020	District: Madhubani
Division: Benipatti	Length (km): 2.60 km
Name of the Road: Chantusa to Nagas	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 319100080308
Status of the Project:	Ongoing/Completed/Under Maintenance out of Maint.
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flt./ slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Not any ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- This road is same road as 'Kachri Chauk to Madhyavidyalaya Narkeshi' which is under Maint and its report submitted.

Signature
02/12/20
(Signature)

NAME: Md. Sani

DESIGNATION: J.E. RND, Div. Benipatti
Sect- Benipatti