

FIELD INSPECTION REPORT

Date of Inspection: 07.12.2020	District: Samastipur
Division: Roxara.	Length (km): 1.55 km
Name of the Road: MDR to Patogi	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: <u>Ongoing</u> /Completed/Under Maintenance	
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	On going
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	N/A
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	Partially.
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Alok

07.12.2020
(Signature)

NAME: ALOK KUMAR

DESIGNATION: J.E