

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Bogusari</u>	
Division : <u>Ba. C/O</u>	Length (km): <u>0.550</u>	
Name of the Road: <u>Repair of Bogusari electric Sahelpur prukhand ke Mathipus Anubodhos phumuk</u>		
Scheme/Programme:	MAINTENANCE <u>Se Samastipur</u>	
Package No.:	Road Id No.: <u>32010608014</u>	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>N/A</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<u>N/A</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:


 (Signature)
 Executive Engineer
 RWD Works Division, Balia