

FIELD INSPECTION REPORT

Date of Inspection :	District: Aurangabad.
Division :	Length (km):
Name of the Road:	Sanday Bel Path Model to Madarpur
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: MR3059014
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI U
c)	Condition of railings/slab/approach for Bridges	S/SRI U
3.	Road Furniture	
d)	Whether sign boards/informatory/cautionary Board km & 200m stone pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Noted Transfered to R&D Rd.

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME:

Randeet Kr.

Randeet
03.12.20
J.G

(Signature)