

FIELD INSPECTION REPORT

Date of Inspection : 07.12.2020 District: panna
 Division : Borth Length (km): 1.0 Km
 Name of the Road: NH-31 Kalyanpur Dhakaula to Khatola to Banya Khore Hc
 Scheme/Programme: MAINTENANCE

Package No.: Road Id No.:
 Status of the Project: Ongoing / Completed / Under Maintenance
 Work is a case of: New Connectivity / Up gradation / Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	SL
a)	Road Junction condition	✓ SL
b)	Condition of Surfacing	SL
c)	Riding Quality	✓ SL
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	S/SRI
a)	Condition of head walls in stone pile culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls slab in RCC culverts	S/SRI
c)	Condition of railings/slab/approach for Bridges	S/SRI
3.	Road Furniture	✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of AFR's & any others	"S"

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

B. P. Singh
 (Signature)

BISHWA PRATAP SINGH
 Junior Engineer.
 NAME: