


FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khajuraho
Division :- Khajuraho		Length (km) :- 1.85
Name of Road :- Lodhna to Machha via Garogaht		
Scheme/Programme :- MP- old		Maintenance
Package No. :-		Road ID No. :-
Status of Project :-		Ongoing/Complete/Under Maintenance <input checked="" type="checkbox"/>
Work is a case of :-		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surface	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <input checked="" type="checkbox"/>
f)	Construction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 3.12.20
 J.E./pland.


FIELD INSPECTION REPORT

Date of Inspection :- 3/12/20		District :- Khajuraho	
Division :- Khajuraho		Length (Km) :- 4.93 km	
Name of Road :- A.J.B to Bhikampurhat via Sakur			
Scheme/Programme :- M.R - old.		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :-		Ongoing/Complete/Under Maintenance <input checked="" type="checkbox"/>	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition		✓ S/U
b)	Condition of Surface		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No <input checked="" type="checkbox"/>
f)	Construction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		HA S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 3/12/20
 J.E. Patel

FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khajuraho	
Division :- Khajuraho		Length (Km) :- 0122 Km	
Name of Road :- Const ⁿ of road from Burhawa to Bhikharighat (Missing Link)			
Scheme/Programme :- MR- New		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :-		<input checked="" type="checkbox"/> Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Upgradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a) -	Road Junction Condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surface	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No <input checked="" type="checkbox"/>
f)	Constrution Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	HA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

FIELD INSPECTION REPORT


Date of Inspection :- 3/12/20		District :- Khajuraho
Division :- Khajuraho		Length (Km) :- 4.9 km
Name of Road :- Chhilkani to Machhwa		
Scheme/Programme :- M.P. - New		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- on going		Ongoing/Complete/Under Maintenance
Work is a case of :-		New Connectivity/Upgradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surface	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contruction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 3.12.20
 J E / Plankhi

FIELD INSPECTION REPORT


Date of Inspection :- 3.12.20		District :- Moga
Division :- Moga		Length (Km) :- 2.45
Name of Road :- Bahadurpur se sonihar		
Scheme/Programme :- old. MR		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- under maintenance.		Ongoing/Complete/Under Maintenance <input checked="" type="checkbox"/>
Work is a case of :-		New Connectivity/Upgradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	SRI S/U
c)	Riding Quality	SRI S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA Yes/No <input checked="" type="checkbox"/>
f)	Construction Joints provided or not (CC Pavement)	HA Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <input checked="" type="checkbox"/>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	HA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	S Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)


 3.12.20
 SE/Alamb.


FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khatiana
Division :- Khatiana		Length (Km) :- 1.55
Name of Road :- Khatiana PWD path se Belagani		
Scheme/Programme :- M.R-New		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- ongoing		Ongoing/Complete/Under Maintenance
Work is a case of :- surface work complete		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surface	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Construction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 3.12.20
 J.E./Khatiana

FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khajuraho	
Division :- Khajuraho		Length (Km) :- 2.10	
Name of Road :- Khajuraho Bakhni pwp road Kathana Railway crossing to Ramnagar - part II			
Scheme/Programme :- old MR		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- Under Maintenance		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No. Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

3.12.20
S.E./Khajuraho

FIELD INSPECTION REPORT

Date of Inspection :- 03.12.2020		District :- Khagaria.	
Division :- Khagaria		Length (Km) :- 3.850 km.	
Name of Road :- Bakhti Khagaria PWD Road To Tribhuvan Gola via Sohrai Phala.			
Scheme/Programme :- MR New.		Maintenance	
Package No. :- —		Road ID No. :-	
Status of Project :- Ongoing.		Ongoing/Complete/Under Maintenance	
Work is a case of :- Up gradation.		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition		S S/U
b)	Condition of Surface		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Construction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		NA S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

3/12/20
J.E. / Khagaria