


FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020		District: Katihar.
Name of Road:		Repair of Road from Katihar (Sanitgum) to Mansahi (Harang)
Scheme/ Programme:		MAINTENANCE (MR 3054)
Package No.		Road ID No.
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2	Gross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	Yes
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	Yes
c)	Condition of railings/slabs/approach for Bridges	Yes
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	S
4	Compliance History	
a)	Status of ATR & any others	No

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Amrendra Nath Thakur
Designation: Junior Engineer.


(Signature)

Note :- यह एवं अतिवृष्टि के कारण अंशिक रूप से क्षतिग्रस्त, मरुभूमि का कार्य समाप्त जा रहा है।