

FIELD INSPECTION REPORT

Date of Inspection :	5.12.2020	District:	Saran
Division :	R.W.D. Madhauri	Length (km):	3.50 km
Name of the Road:	Repair of Dhamauli, Rasauli Panapuri		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31306508028
Status of the Project:	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/> M.R-3057.		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/D

Overall Rating

Surface damage due to flood. Motorable work done

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: ASHUTOSH KUMAR RANJAN

DESIGNATION: A.E.