

FIELD INSPECTION REPORT

Date of Inspection : District: **SIWAN**
 Division : **MAHARAJGANJ** Length (km): **1.60KM**
 Name of the Road: **BASANT PUR VARAPURA ROAD TO MATHIYA**
 Scheme/Programme: **MAINTENANCE**
 Package No.: Road Id No.:
 Status of the Project: **Ongoing/Completed/Under Maintenance**
 Work is a case of: **New Connectivity/Up gradation/ Maintenance**

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

FLOOD DAMAGE

Overall Rating :	Satisfactory (S)	5
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

Mritunjay Kr. Gini

NAME:

A.E

DESIGNATION:

MANISH KUMAR OJHA
(J.E.)

(Signature)

04/12/20
A.E