

FIELD INSPECTION REPORT

Date of Inspection:	03/12/xx	District:	Motihari
Division:	Pakur Daya	Length(Km):	9.0
Name of Road:	Pakur Daya to Dhaka (P-2)		
Scheme/Programme:	Maintenance ✓		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank /slope & raincuts if any	Yes/No ✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓
3	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	✓ "U"

(Signature)

Name:

Designation:

[Signature]
03/12/xx
J. P. S.