

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District: N. Champaran
Division : Belhiab		Length (km): 5.06 km
Name of the Road: Bakhariga to Karamon		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31808408084
Status of the Project: Ongoing/Completed/Under Maintenance		UNDER Maint.
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maint.
Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	U
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	U
c)	Condition of railings/slab/approach for Bridges	U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Amg
(Signature) 12-20

NAME: NARENDRA SINGH

DESIGNATION: EE RWD(N) Div
Belhiab