## FIELD INSPECTION REPORT

Date	of Inspection : (	06/12/200	District: W. Champon	•••	
Division: Detlah			Length (km): 0.175 km		
	of the Road:		( 0 1/ 17 Km	<u> </u>	
Scheme/Programme: M		MAINTENANCI	MAINTENANCE		
	ge No.:		Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be checked		Remarks	
1.	Payement			Areamet no	
a)	Road Junction condition			<u> </u>	
b)	Condition of Surfacing			S/U	
c)				S/U	
	Riding Quality			S/U	
d)	Road Camber			S/U	
e) -	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
	Cross Drainage				

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Condition of railings/slab/approach for Bridges

Overall Rating

a)

b)

c)

3.

a)

4.

a)

Road Furniture

Compliance History

Status of ATR's & any others

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: Road Construct by RWD works.

(Signature)

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No

NAME:

**DESIGNATION:**