

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: Samastipur
Division : Dalsing Sarey		Length (km): 9.0
Name of the Road: Repair of road from Chaura Tabhara to Khoksaha, MR old.		
Scheme/Programme: MAINTENANCE		Road Id No.:
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing (Surface damage during Flood.)	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Flood damage entry in M.I.S.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

due to flood

NAME: Ramesh K. Singh

DESIGNATION: JE

04/12/2020
(Signature)