

FIELD INSPECTION REPORT

Date of Inspection :	District:
Division :	Length (km): <i>6.5</i>
Name of the Road:	<i>Chafra ngor to Deewai</i>
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: <i>MR 2084 old</i>
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & cuttings if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Taragad to RCU Rd.
Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

03-12-20
J-E

(Signature)

NAME: