

FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020 District: B/163 P U R (Area)
 Location: A-2 Length (km): 5.200 Km.
 Name of the Road: Arasikere Road (Vidyanagar) to Pijaniya (PUD Area) via Police Station Road
 Scheme/Programme: MAINTENANCE
 Project No.: Road Id No.: 104-01600836
 Status of the Project: Ongoing/Completed Under Maintenance ✓
 Work in case of: New Connectivity/Up gradation/ Maintenance

S. No.	Parameters to be checked	Remarks
1.	Pavement	
1.1	Road Junction condition	✓ S/U
1.2	Condition of Surfacing	✓ S/U
1.3	Riding Quality	✓ S/U
1.4	Road Camber	✓ S/U
1.5	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
1.6	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
1.7	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
2.1	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
2.2	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
2.3	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
3.1	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
4.1	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 06/12/2020
 J. E.

(Signature)

NAME: