FIELD INSPECTION REPORT

Date of Inspection: 2-12-2020			District: Rohm	
Division: Sa Sazan-/			Length (km): 4.03 Km	
	f the Road:	my good 1	on Ame Talos to Rad	K. Nahl
_	/Programme:	MAINTENANC	The state of the s	
Packag	f the Project:	Danning/Comple	Road Id No.: sted/Under Maintenance	
Market Street Co.	a case of:	The Control of the Co	y/Up gradation/ Maintenance	-
SL No.			Remarks	
ı.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			-S/U
d)	Road Camber			~8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ð	Contraction Joints provided or not (CC Pavernent)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Desires Co. Sec. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance H	story -	Link News	1 4
a)	Status of ATR's & any others			MO

Overall Rating

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

Umesn

DESIGNATION: J.F.