

**FIELD INSPECTION REPORT**

Date of Inspection :	3-12-20	District:	Rohru
Division :	Sector-1	Length (km):	2.83
Name of the Road:	PWD Road to Tendu village		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	<b>Pavement</b>		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & rincuts if any		Yes/No
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	<b>Road-Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	<b>Complaints History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE - WORK ON PAVING TIL

*Per*  
3/12/20  
(Signature)

NAME: VME8Y

DESIGNATION: JC