

FIELD INSPECTION REPORT

Date of Inspection :	27-12-2020	Station :	BANKA
Division :	BANKA-2	Length (km):	5.28
Name of the Road:	Naurada Dhoraiya Road To Makaita Road		
Scheme/Programme:	MAINTENANCE		
Contract No.	MR(101d)	Project No.	20703600825
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Condition of Quantity	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A	
b)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A	
3.	Signage		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATRs & any orders	—	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: AJAY KUMAR

DESIGNATION: Asst