

FIELD INSPECTION REPORT

Date of Inspection : 08-12-2020		District: Madhubani	
Division : Jhantapur.		Length (km): 3.300	
Name of the Road: Malicham-to chandushwar asthan harkhi path			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.: 31909800824	
Status of the Project:		Ongoing/Completed/Under Maintenance <u>Ongoing</u>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓ U
b)	Condition of Surfacing	S/U ✓ U
c)	Riding Quality	S/U ✓ U
d)	Road Camber	S/U ✓ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NO
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Dhananjay Kumar
08.12.2020
(Signature)

NAME: Dhananjay Kumar,

DESIGNATION: J.E