

FIELD INSPECTION REPORT

Date of Inspection: 07.12.2020		Blot-dot: DASHA
Division: BANKA - 2	Length (km): 1.60	
Name of the Road: Dhoraiya Sanhaua Road To Chak Mathura Road		
Scheme/Programme:	MAINTENANCE	
Package No.: MR (otd)	Road Id No.: 20703600828	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl No.	Parameters to be checked	Remarks
1.		
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contractors limits specified or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U M/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U M/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATP's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)
07.12.2020

NAME: AJAY KUMAR
DESIGNATION: AE