FIELD INSPECTION REPORT

Date	of Inspection : 08.12.20 District: East chan	pparau	
Divisi	Langth (km): 1.7.	Length (km): 17.0 KM	
	cof the Road: Brelaki to Norsa		
	ne/Programme: MAINTENANCE 3054 nge No.: Road Id No.: 3176	261.843	
		082800	
	s of the Project: Queoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance New Connectivity/	icc	
Sl. No	Contraction of the Contraction of Contraction Contract	Remarks	
1.	Pavement	and the same of th	
<u>u)</u>	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality	✓\$/() ~. #\$/U	
d)	Road Camber S/U		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement) Yes/No		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including i	ts painting S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culve	rts S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
1.	Compliance History		
1)	Status of ATR's & any others	N.A.	

Overall Rating

Satisfactory (S)	(51
Satisfactory but requires Improve	ment (SRI)
Unsatisfactory (U)	

(Signature)

NAME: Mithilesh Kumar Singh

DESIGNATION: Jurior Engineer, Rexauf