


FIELD INSPECTION REPORT

Date of Inspection : 05-12-2020		District: Saran Chapra
Division : Malhauya		Length (km): 5.50 km
Name of the Road: Gopalbazar to Kumbhailaya Doyla path		
Scheme/Programme: MAINTENANCE		
Package No.:		
Status of the Project:	Road Id No.: 31306500829	
Work is a case of:	Ongoing/Completed/Under Maintenance	
	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No MA
g)	Compaction of flank/slope & raincuts if any	Yes/No MA
2.	Cross Drainage	✓ Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	✓ S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	



(Signature)

NAME: Kausar Ali

DESIGNATION: J.E.