

# FIELD INSPECTION REPORT

Date of Inspection : 07.12.2020	District: Madhubani
Division : R.W.D (W.D) Phulpur	Length (km): 2-10 km
Name of the Road: SH. to Huda	
Scheme/Programme: MAINTENANCE	31909900819
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A *
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A *
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	} S/SRI/U N.A *
c)	Condition of railings/slab/approach for Bridges	
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

\* N A = Not Applicable

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*(Signature)*  
7.12.2020

NAME: JITENDR KUMAR

DESIGNATION: A.E