## FIELD INSPECTION REPORT

Date of Inspection : of	5 12 2020	District: Saran	
Division: Marhaura		Length (km): 7.0 km	
Name of the Road: May	tratch-lathant	our road chainfour to Balua via Bahad	
Scheme/Programme:	MAINTENANCE	Chhapia, Sapahi Path	
Package No.:		Road Id No.: 31306500834	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

	, PB	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	_S/U
d)	Road Camber	√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	H BYes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U n
3.	Road Furniture	The Marian
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	4.

(Signature)

NAME: ASHUTOSH KUMARRANJAM

DESIGNATION: AE