

out of Maintenance

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Bhogpur</u>	
Division : <u>Area</u>		Length (km): <u>2.5 Km</u>	
Name of the Road: <u>Pajga to Bagantpur</u>			
Scheme Programme: <u>MAINTENANCE</u>		<u>Maintenance Roadside Jct</u>	
Package No.:		Road Id No.:	
Status of the Project: <u>Ongoing / Completed Under Maintenance</u>			
Work is a case of: <u>New Connectivity / Up gradation / Maintenance</u>			

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	<u>N.A</u>
b)	Condition of Surfacing	S/U	<u>N.A</u>
c)	Riding Quality	S/U	<u>N.A</u>
d)	Road Camber	S/U	<u>N.A</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	<u>N.A</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	<u>N.A</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No	<u>N.A</u>
2.	Cross Drainage		
a)	Condition of head walls in Home pipe culverts including its painting	S/SR/U	<u>N.H</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	<u>N.H</u>
c)	Condition of railings/slab/approach for Bridges	S/SR/U	<u>N.H</u>
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No	<u>N.H</u>
4.	Compliance History		
a)	Status of ATR's & any others		<u>No</u>

Overall Rating :

Satisfactory (S)	<u>N.A</u>
Satisfactory but requires Improvement (SRU)	
Unsatisfactory (U)	


 (Signature)

NAME: