

FIELD INSPECTION REPORT

Date of Inspection: 5.12.21 District: Bhagpur
 Division: A-20 Length (km): 4.230 Km
 Name of the Road: Gundi Bhakura Road
 Scheme Programme: MAINTENANCE
 Package No.: Road Id No.:

Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No
Compliance History		
	Status of ATR's & any others	No

Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	N.A
Unsatisfactory (U)	

(Signature)
 5.12.21