

FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020 District: BHOLPUR (Ara)
 Location: Ara
 Length (km): 3.760 Km.
 Name of the Road: Ara Buxar Road (NH-89) to Madanpur Khat railway station.
 Scheme Programme: MAINTENANCE
 Package No.: 5292 Road Id No.: 10401608160
 Status of the Project: Ongoing/Completed/Under Maintenance ✓
 Object of the case of: New Connectivity/Up gradation/ Maintenance

S. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones Pavement road markings are provided and maintained	200m Yes/No N.A
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

06/12/2020
J-E

(Signature)