

FIELD INSPECTION REPORT

DATE OF INSPECTION:	08.12.2020 DISTRICT:-PURNEA	
DIVISION:	DHAMDAHA ,LENGTH: 14.71 km.	
NAME OF THE ROAD:	Bhadrapur Rajdham to Sripur, mile. .	
SCHEME/PROGRAMME:	MAINTENANCE MR3054-OLD	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	/
B	CONDITION FO SURFACING	
C	RIDING QUALITY	
D	ROAD CAMBER	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	H.A.
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	/
4	COMPLIANCE HISTORY	
A	STATUS OF ATR"s & ANY OTHERS	H.A.
OVERALL RATING	Transferred RCD	
	SATISFACTORY(S)	/
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
	UNSATISFACTORY(U)	

NAME: Kumar Chayson
DESIGNATION: J.E

14/12/2020
8/12/2020
SIGNATURE