

FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	Buxar
Division :	R.W.D. Buxar	Length (km):	1.30 Km.
Name of the Road:	UNIMOS to Tigra Basav Kala Road to Chandi Road		
Scheme Programme:	MAINTENANCE		
Package No.:	MR-N/19-20, Buxar/01	Road Id No.:	-
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity Up gradation Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓SU	
b)	Condition of Surfacing	✓SU	
c)	Riding Quality	✓SU	
d)	Road Camber	✓SU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No NA	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

[Signature]
3.12.2020
J.B

[Signature]
03/12/20
(Signature) AT