Inspection of Roads Under MR (3054) in Chausa block

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	**District:** Buxar
Division : Buxar	**Length (km):** 1.871
Name of the Road: NH85 to Kathgharawa Under MR(3054) New Policy 2018.	
Scheme/Programme:	MAINTENANCE
Package No.:	**Road Id No.:**
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	~~S/SRI/U~~ N.A.
c)	Condition of railings/slab/approach for Bridges	~~S/SRI/U~~ N.A.
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

MNPrasad 03.12.2020
(Signature)

NAME: Maya Nand Prasad

DESIGNATION: J.E.