


Inspection of Roads Under MR (3054) in Chauva Block

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Buxar	
Division : Buxar		Length (km): 1.527	
Name of the Road: Chauva-Ramgarh Road to Aharampura (Tiwary) Under MR (3054) New Block			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No	N.A.
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N.A.
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 03.12.2020

NAME: Maya Nand Prasad

DESIGNATION: J. E.