

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Patna</u>
Division : <u>BARH</u>	Length (km): <u>1.90</u>
Name of the Road: <u>Baniyarpur Itawa Rd to Rest part of Dhanawan village</u>	
Scheme/Programme: <u>MAINTENANCE</u>	
Package No.:	Road Id No.:
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>	<u>DPK submitted for Review AA to Department</u>
Work is a case of:	<u>New Connectivity/Up gradation/ Maintenance</u>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings/slab/approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME:

(Signature)

EXECUTIVE ENGINEER
R.W.D. WORKS DIVISION
BARH