FIELD INSPECTION REPORT

Date of Inspection : O	8-12-2020	District: Awargabad	
Division: Dandragor		Length (km): 0.750 km	
		1. to Hathikhaf	
Scheme/Programme:			
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
CL N.	The State of the S	to be absolut	-

Sl. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History	E PARK		
a)	Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Terdorof This Rd. is not decided.

(Signature)

NAME: Shubban ke

DESIGNATION: J.C.