

This road is in progress

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020	District: AURANGABAD	
Division : AURANGABAD	Length (km): 2.07	
Name of the Road: KUNZIGWALY TO BAZZANAN.		
Scheme/Programme:	MAINTENANCE N/R 3054 New maint. Policy-	
Package No.: N/R-N/19-20 AUR AD/31	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U.
d)	Road Camber	Yes/No N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	200m Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: Dinesh Prasad Singh