FIELD INSPECTION REPORT

	4		Se front		
Date of I	nspection: d	22/12/20	District: Banka		
Division: Banka / Length (km): 2.720					
Name of	the Road: An	norther Shahl	und Road to vjagarkitt	3	
Scheme/l	Programme:	MAINTENANC	CE		
Package	No.: RM/BF	A/BAN/20/0	002 Road Id No.: 2070350201	9	
	the Project:		eted/Under Maintenance		
The first of the second			ty/Up gradation/ Maintenance		
Sl. No.		Parameter	s to be checked	Remarks	
	Payement				
a)	Road Junction	condition		S/U	ongoing
b)	Condition of S	Surfacing		S/U	onguing
c)	Riding Quality	у		S/U	ongoing
d)	Road Camber S/U				onleing
e)		e from defects case of CC Paverr	such as visible cracks, exposed nent.	Yes/No	ongoing ongoing ongoing NA
f)	Contraction Jo	oints provided or 1	not (CC Pavement)	Yes/No	NA
g)	Market I and the Control of the Cont	of flank/slope & ra	incuts if any	Yes/No	
2.	.Cross Draina	ige			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U				ongoing
c)	Condition of railings/slab/approach for Bridges S/SRI/U				ongoing
3.	Road Furnit	ure			
a)			tory/cautionary Board/km & 200m s are provided and maintained	Yes/No	onfoing
4,3	Compliance	History			
a)	Status of ATI	R's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ellinal 02/12/20 (Signature)

NAME: DHARMVEER NUMAR

DESIGNATION: J. E.