

BMOREY

Date of Inspection : 08.12.2020		District: GOPALGANJ	
Division : HATHUA		Length (km): 6.60	
Name of the Road: SISAI & RAMPUR			
Scheme/Programme: MAINTENANCE			
Package No.: MA-N/19-20 Hathua/11		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	N/A	S/U
b)	Condition of Surfacing	N/A	S/U
c)	Riding Quality	N/A	S/U
d)	Road Camber	N/A	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N/A
4.	Compliance History		
a)	Status of ATR's & any others	NO any	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N/A

Surfacing Work has not started.

(Signature) [Signature] 08/12/2020

NAME: Arun Kumar Singh

DESIGNATION: JE