

FIELD INSPECTION REPORT

Date of Inspection : 5/12/20 District: Sonwan
 Division : Mahasarakham Length (km): 4.10 km
 Name of the Road: Bagan to Pansa
 Scheme/Programme: MAINTENANCE
 Package No.: MR-15-20-N-22 Leggy Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A
b)	Condition of Surfacing	1/
c)	Riding Quality	"
d)	Road Camber	"
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	"
g)	Compaction of flank/slope & raincuts if any	Started partly
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

NAME: Ram Sagar Das

(Signature) [Signature]
J-E