

# FIELD INSPECTION REPORT

Date of Inspection :	5/12/2020	District:	Sa'wari
Division :	Maharajganj	Length (km):	3.650 Km
Name of the Road:	NH to Swanbighar		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/20-21 Maharajganj/03	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	B.T. has not done
a)	Road Junction condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	Done partly
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No any

Overall Rating :

Satisfactory (S)	not repair & flank work partly	"S"
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: Ram Sagar Das  
7/12/20  
DESIGNATION: J-E

Rms  
5/12/20  
(Signature)