

FIELD INSPECTION REPORT

Date Of Inspection :

District: Siwan

Division: Mahrajanj

Length(KM) :

2.75 KM

Name Of the Road : Hariharpur To Sadipur

Scheme/Programme :

MAINTENANCE

Package No. : MR-N/19-20Mahrajanj/07

Road Id No. :

Status Of the Project :

Ongoing/Completed/Under Maintenance

Work is a case of :

New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be Checked	Remarks
---------	--------------------------	---------

1 Pavement

a) Road Junction condition

S/U

b) Condition of Surfacing

S/U

c) Riding Quality

S/U

d) Road Camber

S/U

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.

Yes/No

f) Contraction Joints provided or not (CC Pavement)

Yes/No

g) Compaction of flank/slope & raincuts if any

Yes/No

2 Cross Drainage

a) Condition of head walls in Hume pipe culverts including its painting

S/SRI/U

b) Condition of Abutment & Wing walls, Slab in RCC culverts

S/SRI/U

c) Condition of railings/slab/approach for Bridges

S/SRI/U

3 Road Furniture

a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained

Yes/No

4 Compliance History

a) Status of ATR's & any others

No

Overall Rating :

Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

—

Unsatisfactory (U)

—

NAME :
DESIGNATION :

ANAND KUMAR
AE

Amu
5/12/20
(Signature)

5/12/20
MANISH KUMAR OJHA (J.E.)