

## FIELD INSPECTION REPORT

Date Of Inspection :	5.12.20	District: Siwan	
Division:	Mahrajganj	Length(KM) : 7.75	
Name Of the Road : Chitali To Dudhara			
Scheme/Programme :		MAINTENANCE	
Package No. : MR-N/19-20Mahrajganj/07   Road Id No. :			
Status Of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be Checked		Remarks
1	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.		Yes/No <span style="margin-left: 20px;">No provision</span>
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		S/SRI/U <span style="margin-left: 20px;">No provision</span>
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls,Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME :  
DESIGNATION :

ANAND KUMAR  
AE

MANISH KUMAR OJHA (J.E.)

05/12/20

  
(Signature)