

FIELD INSPECTION REPORT

Date of Inspection : District: Bhopal
 Division : ARA- Length (km):
 Name of the Road: Bahiyaria Kolwer path to Farhanpur On 30/04/20
 Scheme/Programme: MAINTENANCE (M.PCC) Road
 Package No.: Road Id No.: NEA 220001469
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: New Connectivity Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU ✓
b)	Condition of Surfacing	SU ✓
c)	Riding Quality	SU ✓
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction joints provided or not (CC Pavement)	Yes/No
g)	Construction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones, pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
 Satisfactory but requires Improvement (SRI) **S-N/A**
 Unsatisfactory (U) **NEA**

Min/Naresh Phadap
 JC
 10/05/20

(Signature)