

FIELD INSPECTION REPORT

Date of Inspection: 7-12-20
 District: West Champaran
 Location: Balkech
 Name of the Road: Keshada Pith to Kungolahi Path
 Scheme/Programme: MAINTENANCE
 Package No.: 99-14(13-74 Balkech of
 Road Id No.: H/A 2/15015
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U H/A
c)	Riding Quality	S/U H/A
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in stone pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: R. J. B. B.

DESIGNATION: J. C.