

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Saran	
Division : Sopur	Length (km): 4.40	
Name of the Road: Dighiar Bherde road to Bishambarpur		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Work not started due to govt

✓ 2/12/22
(Signature)

NAME: Vinod Kumar Singh

DESIGNATION: J.E

Dasipur