

# FIELD INSPECTION REPORT

Date of Inspection :	8/12/20	District:	Vaishali
Division :	Mahmur	Length (km):	7.25 km.
Name of the Road:	Jusauwampur Chalebinger Vishnuapur Bagdan Road		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N 14-20 / Mahmur-B	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>In C/S Process</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	NA S/U
b)	Condition of Surfacing	NA S/U
c)	Riding Quality	NA S/U
d)	Road Camber	NA S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	NA Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NA Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*14*  
8/12/20  
(Signature)

NAME: NAND KISHOR SHARMA

DESIGNATION: J. E. Engineer